

These devices are supported on the latest version of firmware. Please ensure you are running the most recent firmware to ensure device compatibility.

Updated 3/8/2010 (Contact us or visit <http://www.cradlepoint.com> for latest compatibility list)

3 (UK)

Huawei E156G

Alltel

Franklin CDU550 Huawei
EC168/C Huawei EC228
Pantech UM175
UTStarcom UM150
(Pantech UM150)

AT&T

Option QuickSilver Sierra Wireless 881U Sierra Wireless 875U USBConnect 881 USBConnect Mercury
USBConnect Lightning ZTE MF636 Option GT Max 3.6 Express Option GT Ultra Express Blackberry 8310
(Curve) Blackberry 9000 (Bold) HP iPaq 910 Motorola RAZR v3xx Motorola Q v9h Samsung Blackjack
Samsung SGHA707

BMobile (Japan)

ZTE MF626

Bell (Canada)

Novatel Wireless U760

BridgeMAXX WiMAX

ZTE TU25

Clear 4G

When using the Clear WiMAX network, the following Modem Firmware must be loaded onto the CradlePoint Router.

[Download Modem Firmware 5.2.206](#)

Clear USB Modem Clear USB 4G Modem Franklin U300 (3G and 4G)

Comcast HighSpeed2Go

When using the Comcast HighSpeed2Go network, the following Modem Firmware must be loaded onto the CradlePoint Router

[Download Modem Firmware 5.2.206](#)

Franklin CMU300 (3G and 4G) ZTE
TU25

Cricket

Calcomp a600
Pantech UM100
Pantech UMW185

EMobile (Japan)

D02HW
D11LC
D12LC
D21HW
D21LC
D22HW

nTelos

Franklin CDU680
Kyocera KPC680

NTT Docomo (Japan)

LG L02A

O2 (UK)

Sierra Wireless Compass 889U

Orange (UK)

Huawei E160E

Pioneer Cellular

Franklin CDU680 Sierra Wireless USB 598 Sierra Wireless Aircard 402

Rogers (Canada)

Novatel MC950D ZTE MF636 (Rocket Stick) ZTE MF668 (Rocket Stick) Novatel X950D

Softbank (Japan)

Softbank C01LC

Generic UMTS/GSM Devices

These devices were tested using the AT&T network in the United States and may or may not work with other UMTS/GSM carriers internationally.

Huawei E220 Huawei E160E Orange Branded Novatel MC930D Novatel MC950D Sierra Wireless 880U Sierra Wireless 885U (Compass 885) ZTE MF626 Sierra Wireless 880E Huawei E870 Huawei E870 - Orange Branded

Generic CDMA Devices

These devices were tested on CDMA networks that have approved these devices for use around the world and may or may not work with carriers that have approved them for Huawei EC168C Sierra Wireless USB 598 Sierra Wireless Aircard 402

Sprint

When using the Sprint WiMAX network, the following Modem Firmware must be loaded onto the CradlePoint Router

[Download Modem Firmware 5.2.206](#)

Franklin U300 3G/4G Franklin U301 3G/4G Franklin CDU680 Novatel MiFi 2200 Novatel U720 Novatel U727 Novatel U760 Sierra Wireless 595U Sierra Wireless Compass 597U Sierra Wireless Compass 598U Novatel EX720 Novatel C777 Sierra Wireless Aircard 402 Sierra Wireless 597E Blackberry 8703e Blackberry 8130 Blackberry 8330 Blackberry 8830 HTC Touch HTC Mogul (6800) HTC Apache (6700) LG Fusic LX500 LG Muziq Motorola KRZR Motorola RAZR V3c Motorola RAZR2 Motorola Q Motorola Q9c Palm Centro Palm 700w Palm 755p Samsung A900 Samsung A900M Samsung A920 Samsung ACE Samsung i830 Samsung SPHm520 Sanyo SCP8400 Sanyo Katana Sanyo Katana 2 Sanyo M1

Telus (Canada)

Sierra Wireless U306 Sierra
Wireless 595U Sierra
Wireless 597U Sierra
Wireless 598U Sierra
Wireless 597E

Time Warner Cable Roadrunner Mobile 4G

When using the Roadrunner Mobile 4G network, the following Modem Firmware must be loaded onto the CradlePoint Router

[Download Modem Firmware 5.2.206](#)

Franklin CMU300 (3G and 4G) Franklin
U301 (3G and 4G) Motorola 25w100

TMobile

Huawei UMG181 Option
GE442

TMobile (UK)

ZTE MF637

Verizon

Novatel MiFi 2200 Novatel
USB720 Novatel USB727
Novatel USB760 Sierra
Wireless 595U Pantech
UM150 Pantech UM175
Pantech UMW190 Kyocera
KPC680 Novatel V740
Novatel PC770 Blackberry
8703e Blackberry 8130
Blackberry 8330 Blackberry
8830 Blackberry 9530
(Storm) LG VX7200 LG
VX8000 LG VX8300 Motorola
RAZR V3c Palm 700p Palm
700w Verizon XV6800

Virgin Mobile

Novatel MC760

Vodafone (UK)

Huawei K3565

¹The user experience with devices running Windows Mobile is less robust than other phones and modems. Windows Mobile devices connected to either a PC or a CradlePoint router have exhibited erratic behavior while using data sharing capabilities. Issues include frequent disconnects for no apparent reason and remedies entail frequent rebooting the phone and or removing the phone's battery. This problem is not something that can be resolved by CradlePoint Technology and will need to be addressed by the phone manufacturer. Please refer to Cradlepoints [FAQ](#) section as well as the [release notes](#).